

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria

No. 137 (Temporary) of 2011

LIGHTHOUSE POINT- CORNER INLET -Victoria

Date: EFFECTIVE IMMEDIATELY

Details:

Mariners are advised that a new directional light has been installed at Lighthouse Point, Corner Inlet.

The light has the same characteristics as the previously operating light.

Corner Inlet	38 50.55 S	FI W 5s	36m 17M	<i>f</i> 1.	
-Lighthouse Point	148 28.45 E				Vis 187° -350° (163°)
-- Dir Lt 277°		Dir WRG	35m 9M	FI G 3s 272°-276° (4°)	
				FI W 3s 276°-278° (2°)	
				FI R 3s 278°-282° (4°)	

Mariners navigating in the vicinity are requested to report any issues associated with the light characteristics to laurie.campbell@marys.com.au

AUS Charts and publications referenced:

AUS 181 AUS357
Australia Pilot, Volume II NP14

Admiralty List of Lights and Fog Signals Vol K NP83, 2011/12- K2502

Victorian Charts and Publications affected:

Nil

Further notice:

A further Notice will be issued.

Peter Corcoran
Director, Maritime Safety

25 November 2011