



VICTORIAN NOTICE TO MARINERS No. 086 - 13

Local Port of Portland Bay Establishment of navigational buoys

Date: Wednesday, 26 June 2013
Charts affected: Aus 140
Publication affected: NP14 Australian Pilot, Volume 2
Buoyage system: IALA buoyage system – Region A

Details:

Mariners are advised that east cardinal buoys have been established in the marina in the following positions:

- Lat. 38° 20.691'S, Long. 141°36.602'E
- Lat. 38° 20.742'S, Long. 141°36.522'E

The buoys are displaying light characteristics VQ (3) 5 secs, and indicate safe water to the east.

Mariners are advised to navigate with caution in the proximity of the buoys. No vessel is to moor to the buoys at any time.

Issued by:

A handwritten signature in blue ink that reads "D. I. Shennan". The signature is written in a cursive, flowing style.

Captain David Shennan
Harbour Master
Office: 5525 0980
Mobile: 0439 209 120
E-mail: dshennan@portofportland.com.au