

VICTORIAN NOTICES TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 10 December 2014

AUSTRALIA – VICTORIA

No. 208(T) - 2014

PORT PHILLIP – PORT MELBOURNE CHANNEL

DAMAGE TO No. 74 BEACON – TEMPORARY LIGHT ESTABLISHED

Date: Effective immediately.

Details: Mariners are advised that Port Melbourne Channel No. 74 Beacon located in position 37° 51.30' S 144° 55.68' E has been damaged causing the light and top mark to be out of commission.

A temporary light with characteristics Fl(2)R 4s 2m has been installed and will remain in place whilst works are undertaken to repair the beacon.

Repair works are scheduled for completion on or about 20 December 2014.

Mariners are advised to navigate with caution in the vicinity of the beacon.

Charts affected: AUS 154, AUS 155

Further notice: A further notice will be issued.

**ROY STANBROOK
HARBOUR MASTER**

This notice is a direction of the Harbour Master pursuant to section 232 of the Marine Safety Act 2010.
The requirements of section 232(2) have been taken into account.