

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 28 September 2017

Australia – Victoria

No. 247 - 2017

Port of Port Phillip

**St Kilda - Royal Melbourne Yacht Squadron Marina
Submerged rocks at the north-western entrance to the Marina**

Date: Immediate

Details: Mariners are advised of rocks approximately 1.8m (chart datum) below the surface, and approximately 7m to the east of the breakwater, at the entrance to the marina between the wave attenuator and the rock breakwater between approximately 37°51.650'S, 144°57.746'E and 37°51.660'S, 144°57.753'E (WGS84).

Vessels are advised to keep at least 8m from the rock breakwater when entering the RMYS Marina between the wave attenuator and the breakwater to avoid rocks on the breakwater toeline.

Mariners are advised to navigate with caution when navigating within the vicinity of the RMYS Marina Entrance. Inbound vessels should give way to outbound vessels to avoid going close to the breakwater. The breakwater rocks extend approximately 7m into the marina fairway from the waterline.

Charts & Publications

Affected: AUS 143 & 155

Further Notice: No further Notice will be issued.

If you require any further information, please contact Damien Ryan at the Royal Melbourne Yacht Squadron on 03 9534 0227

Ledene McGregor
A/Senior Manager Local Ports & Waterways
Melbourne Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.