

## VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

### GEELONG, 1 JANUARY 2018

### AUSTRALIA - VICTORIA

### NO. 001(T)-18

### VICTORIAN NOTICE TO MARINERS

### NOTICES IN FORCE

- Date:** On the 1<sup>st</sup> January 2018
- Former Notice:** 001(T)-17 refers and is hereby cancelled.
- Details:** The following Victorian Notice to Mariners are in force.
- Notices can be downloaded from:  
Victorian Regional Channels Authority (VRCA) website  
[www.regionalchannels.vic.gov.au](http://www.regionalchannels.vic.gov.au)
- Victorian Ports Corporation Melbourne (VPCM) website  
[www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)
- Parks Victoria website  
[www.parks.vic.gov.au](http://www.parks.vic.gov.au)

<u>Notice No</u> <u>2005</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
68	Port of Hastings	Port of Hastings	Port of Hastings	Maritime Transport Security Regulations 2003 Restricted Zones – Crib Point & Long Island Point Jetties
71	Port of Hastings	Port of Hastings	Port of Hastings	Maritime Transport Security Regulations 2003 Restricted Zones – Correction to Position of Pile CP4

<u>Notice No</u> <u>2006</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
18	Port of Hastings	Port of Hastings	Port of Hastings	Stony Point Jetty Lead Lights
53	Barwon Coast	Port of Barwon Heads	Barwon Heads River Entrance	Sand Movements – Possible Reduction in Depth

<u>Notice No</u> <u>2007</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
140(T)	Barwon Coast	Port of Barwon Heads	Port of Barwon Heads	Orungal Wreck Hazard – East of River Entrance

<u>Notice No</u> <u>2008</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
64(T)	Port of Hastings	Port of Hastings	Channel Off Sandy Point	Shoaling in Channel Between Nos. 13 and 15 Buoys
65(T)	Parks Victoria	Port Phillip	Outer Harbour	Abalone Farm Dislodged Pipelines, Leopold

<u>Notice No</u> <u>2010</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
33	Port of Hastings	Port of Hastings	Port of Hastings	Single Pile Beacons at Crib Point Jetty & Flinders Aquaculture Lease Area

<u>Notice No</u> <u>2011</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
100	Gippsland Ports	Port of Corner Inlet and Port Albert	Corner Inlet Inner Entrance, Bentley Point	Alteration to Navigation

<u>Notice No</u> <u>2013</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
017	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Channel	Isolated Danger Buoy Established
048	Port of Hastings	Western Port	Flinders Pile	Flinders Pile Beacon Light
065	Gippsland Ports	Port of Corner Inlet and Port Albert	Corner Inlet Entrance	Alteration to Navigation Systems
130	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Entrance	Anderson Inlet Entrance Navigation Warning
173(T)	Gippsland Ports	Port of Corner Inlet & Port Albert	Port Anthony Marine Terminal	Berth Pocket Surveyed – Depths Declared Aids to Navigation Established

<u>Notice No</u> <u>2014</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
006	Port of Hastings	Western Port	Western Port	An AIS A to N – Established on trial basis on Buoy No. 8
029(t)	Gippsland Ports	Port of Anderson Inlet	Vicinity of Point Smythe	Establishment of Speed Restriction Zone
213	Colac Otway	Port of Apollo Bay	Harbour Entrance	Harbour Entrance Reduced by Sand – Extreme Caution to be taken
223	Gippsland Ports	Port of Mallacoota	Bastion Point Breakwater & Boat Ramp Facility	Navigation Aids Established – Safety Warning

<u>Notice No</u> <u>2015</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
064	Gippsland Ports	Port of Corner Inlet & Port Albert	Welshpool Pier	Floating Timber Debris
088	Gippsland Ports	Port of Corner Inlet & Port Albert	Lewis Channel	Approach to Port Welshpool – Channel Shoaling
108	Gippsland Ports	Port of Corner Inlet & Port Albert	Port Albert Fairway Buoy	Relocated
122(T)	MSV	Port Fairy	Griffith Island Light	Griffith Island Light - Warning
131	Gippsland Ports	Port of Gippsland Lakes	Lakes Entrance – North Arm	Starboard Hand Beacon No. 11 has been lit
132	Gippsland Ports	Port of Gippsland Lakes	Reeve Channel	Leads Withdrawn – Unlit Buoy Withdrawn – Lit Starboard Hand Lateral Buoy Established
138	Gippsland Ports	Port of Corner Inlet & Port Albert	Port Albert Inner Entrance	Beacon Characteristics Altered
173	Barwon Coast	Local Port of Barwon Heads	Barwon Heads - Ocean Grove Spit	Land Based Aid to Navigation Marks – Ocean Grove Spit for Approach to Barwon River Entrance
177	Gippsland Ports	Port of Gippsland Lakes	Lakes Entrance	Cunninghame Arm Compass Adjustment Pile has been lit
188	Gippsland Ports	Port of Corner Inlet & Port Albert	Port Albert Inner Entrance	Front Lead – Characteristics Altered
199(T)	MSV	Port Fairy	Taylor's Bay	Deployment of Cardinal Mark Buoys
217(T)	MSV	Port Fairy	Taylor's Bay	Exclusion Zone and Transit Lane Establishment
238	Barwon Coast	Local Port of Barwon Heads	Barwon River Entrance	Sector Light Aid to Navigation
250(T)	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Bar	Marine Incident – Vessel Missing
255	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Bar	Warning to Vessel Operators Who Intend to Risk Bar Crossing at Anderson Inlet Ocean Entrance

<u>Notice No</u> <u>2016</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
005	Gippsland Ports	Port of Mallacoota Inlet	Bastion Point Boat Ramp	Notices Cancelled
029(T)	Parks Victoria	Port Phillip	Mornington	Mornington Pier Navigation Light - Missing
038	Barwon Coast	Local Port of Barwon Heads	Barwon River Navigation Channel	Shallow Ground
134(T)	Parks Victoria	Port Phillip	Wyndham Harbour	Installation of Four Temporary Berthing Piles
147(T)	Parks Victoria	Port Phillip	Wyndham Harbour	Installation of One Temporary Berthing Pile
152	Gippsland Ports	Port of Mallacoota Inlet	Bastion Point	Victorian Government Gazette – Notice of Waterway Rule Change
165	Gippsland Ports	Port of Mallacoota Inlet	Genoa River & Mallacoota Lakes	Flood Water Warning
170(T)	Gippsland Ports	Port of Mallacoota Inlet	Bastion Point – Ocean Access Boat Ramp	Shoaling – Approach Channel Depths Compromised
191	Gippsland Ports	Port of Corner Inlet & Port Albert	Port Albert Entrance	Fairway Light Buoy Relocated
221	Gippsland Ports	Port of Anderson Inlet	Entrance Bar & Main Channel	Shoaling
227(T)	Gippsland Ports	Port of Gippsland Lakes	Lakes Entrance Bar	Rudder Lost
230	Gippsland Ports	Port of Anderson Inlet	Point Smythe	Speed Restriction Zone Buoys and Isolated Danger Buoy Removed
239(T)	MSV	Port Albert	Shoal Inlet Entrance	Temporary Light Established
250	Gippsland Ports	Port of Corner Inlet & Port Albert	Port of Corner Inlet & Port Albert	Harbour Masters Directions and Port Information Handbook Part 1 – August 2016 Edition
270	Gippsland Ports	Port of Corner Inlet & Port Albert	Franklin River Channel	Navigation Aid Upgrades
271	Gippsland Ports	Port of Corner Inlet & Port Albert	Bennison Creek Channel	Alteration to Navigation Aids
275	Gippsland Ports	Port of Corner Inlet & Port Albert	Corner Inlet Basin – Stockyard Channel	Navigation Aids Established – Navigation Aids Numbered

276	Gippsland Ports	Port of Corner Inlet & Port Albert	Stockyard Creek Channel	Alteration to Navigation Aids
282(T)	Gippsland Ports	Port of Gippsland Lakes	Lakes Entrance Bar	Leads Altered
292(T)	Parks Victoria	Port Phillip	Rye	Port Lateral Buoy - Missing
299(T)	Gippsland Ports	Port of Gippsland Lakes	Reeve Channel	Temporary light Buoy Established
322(T)	VPCM	Port of Melbourne	Yarra River Bolte Bridge	Yarra River – Bolte Bridge Starboard Hand Beacon Missing
327(T)	Gippsland Ports	Port of Mallacoota Inlet	Bastion Point Boat Ramp	Dredging Operations to Continue – Expect Interruptions to Vessel Launching and Retrieval
328	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Bar	WARNING to Vessel Operations Intending to Risk Bar Crossings at Anderson Inlet Ocean Entrance
331	LINX Cargo Group	Port of Hastings	Western Port	Depths Reduced – 800 metres of No. 19 Buoy
344(T)	Gippsland Ports	Port of Corner Inlet & Port Albert	Franklin River Channel	No. 13 Light Beacon Damaged and Unlit

<u>Notice No</u> <u>2017</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
80	Gippsland	Port of Gippsland Lakes	Bullock Island Narrows	Speed Restriction Aids to Navigation Established
125	Gippsland	Port of Corner Inlet & Port Albert	Port Albert Entrance Channel	Outer Starboard Hand Buoy – Light Reinstated to Normal Operation
131(T)	MSV	Port Fairy	Moyne River	Martin Point Light
171(T)	Parks Victoria	Port Phillip	Mud Islands	Marine Protected Area Boundary Marker Pile - Damaged
174(T)	Parks Victoria	Western Port	Hastings	North Arm No. 3 Starboard Lateral Pile - Removed
177(T)	VPCM	Port of Melbourne	Swanson Dock East	Swanson Dock East Berth 1 – Rehabilitation Works
179(T)	MSV	Barwon Heads	Orungal Wreck	Cardinal Mark Buoy Off Station
184(T)	Parks Victoria	Port Phillip	Various	Werribee South to Sorrento – Installation of new & upgrade or removal of existing aids to navigation
198	Gippsland	Port of Gippsland Lakes	Port of Gippsland Lakes	Harbour Masters Directions and Port Information Handbook Part 2 – July 2017 Edition
200	VPCM	Port of Melbourne	Short Road	Short Road Tug Berth Project Extended
214(T)	VPCM	Port of Melbourne	Red Tower PEL Light	Red Tower PEL Light Characteristics Altered
215(T)	VPCM	Port of Melbourne	Yarraville 6	Temporary Berth Closure
226	Gippsland	Port of Gippsland Lakes	Lakes Entrance	TSHD Tommy Norton – Dredging and Equipment Trials
236(T)	Parks Victoria	Port Phillip	Frankston	Frankston Pier Starboard Lateral Navigation Light – Non-operational
245(T)	Parks Victoria	Port Phillip	Portarlington	Installation of Temporary Port Buoys within the Harbour
258(T)	VPCM	Port of Melbourne	Maribyrnong River	Geotechnical Investigation Works
270(T)	Colac Otway	Port of Apollo Bay	Apollo Bay Harbour Entrance	Lead Lights at entrance to the Port of Apollo Bay are not aligned correctly with the current safe entrance channel.
278(T)	VPCM	Port of Melbourne	Williamstown Channel	Shoaling West North west of Beacon 22 Outside of Williamstown Channel
282(T)	Parks Victoria	Port Phillip	Geelong	Cunningham Pier – Floating Christmas Tree – Deployment Works and Display
284(T)	Gippsland	Port of Corner Inlet & Port Albert	Port Welshpool	Stage 2& 3 of the De-construction and Re-construction of the Port Welshpool Pier (Long Jetty)
286(T)	VPCM	Port of Melbourne	Swanson Dock East & West	New Bollard Installation Extended
302(T)	Parks Victoria	Port Phillip	Portsea	Portsea Hole – Submerged Navigation Hazard
313	Port of Hastings	Western Port	Western Port	Cruise Ship Schedule – December 2017 & January 2018
328(T)	Barwon Coast	Local Port of Barwon Heads	Barwon River	Barwon Heads Sailing Association Events Calendar

332(T)	MSV	Bass Strait	East Gippsland	Snowy River Diving Operations
347(T)	Parks Victoria	Western Port	San Remo	Eastern Entrance – South East of Starboard Lateral Pile #1 - Shoaling
351	Barwon Coast	Local Port of Barwon Heads	Barwon River	Isolated Danger – Stork Water Pipe Outfall

**Victorian Notice to Mariners are issued by a number of different Authorities.  
This notice has been collated from the latest information held by the  
Victorian Regional Channels Authority.  
Information relating to the above notices is available at the  
Victorian Regional Channels Authority Website.  
Specific queries relating to Notices should be directed to the issuing Authority.**

**Further Notice:** Further notice will be issued



**CAPTAIN DILIP ABRAHAM  
HARBOUR MASTER  
PORT OF GEELONG**

Victorian Notices to Mariners can be downloaded from the  
Victorian Regional Channels Authority website [www.regionalchannels.vic.gov.au](http://www.regionalchannels.vic.gov.au)