

Melbourne, 18 May 2018

Australia – Victoria
No. 178 (T) – 2018
PORT OF MELBOURNE
WEBB DOCK Bcn 23, 82 and 84
OPERATING AT REDUCED POWER

Date: 18 May 2018

Refers: NTN 175 (T) refers and is cancelled.

Details: Mariners are advised that, Webb Dock Bcns 23, 82 and 84, is now confirmed as lit and operating at reduced power.

Beacon	Characteristic	Approximate Position
Bcn 23	F.G. & Iso.G.4s	37° 50.97'S 144° 54.42'E
Bcn 82	F.R & Fl.R.5s	37° 50.97'S 144° 54.47'E
Bcn 84	F.R & Fl.R.5s	37° 50.88'S 144° 54.44'E

For further information contact Melbourne VTS on 9644 9700.

Mariners are advised to navigate with additional caution when in the vicinity of Beacon 23, 82 and 84


Charts & Publications affected:

AUS 154

Further notice: Further notice will be issued.



**Andrew Hays
Deputy Harbour Master**



NOT FOR NAVIGATIONAL USE

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
 The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au