

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE:07/12/2011

AUSTRALIA - VICTORIA

No. 144-2011

PORT OF CORNER INLET AND PORT ALBERT

FRANKLIN CHANNEL

ALTERATION TO BARGE MOORING BUOYS

DATE: With Immediate Effect.

PREVIOUS NOTICE: NTM 73(T)-2011 is referred

DETAILS: Two Barge Mooring Buoys located in the Franklin Channel have been removed. Mariners are advised that there are currently two Barge Mooring buoys located in the Franklin Channel and that they can have a swing radius of approximately 400 metres.

Details of the current Barge Mooring Buoys are :

FRANKLIN CHANNEL

No.1 Mooring Light Buoy

Characteristic - FI Y 5s.1m 1M

Lat . 38 deg 45.747 min, Long 146 deg 23.918 min.

(AGD66)

Lat -38 deg 45.655 min, Long 146 deg 23.997 min.

(WGS84)

FRANKLIN CHANNEL

No.2 Mooring Buoy

Characteristic - FI Y 5s 1m 1M

Lat . 38 deg 45.730 min, Long 146 deg 24.470 min.

(AGD66)

Lat -38 deg 45.638 min, Long 146 deg 24.548 min.

(WGS84)

CHARTS AFFECTED: AUS 181

PUBLICATIONS AFFECTED: NP14, NP83 (Vol K)

FURTHER NOTICE: A further notice will be issued.

CAPT. TIM HUNGERFORD-MORGAN. HARBOUR MASTER