

VICTORIAN NOTICE TO MARINERS No. 120 - 13

Portland Harbour Revised Speed Limits

Date: Monday 02 September 2013

Charts affected: Aus 140

Publication affected: Australian Pilot, Volume 2 (Twelfth edition 2013) pages 84 – 88

Buoyage system: IALA buoyage system – Region A

Details:

Mariners are advised that the following speed limits are now in force:

- a) **5 knots** - west of a line extending across the harbour from the NW Corner (38° 20.9'S, 141°36.8'E) to Lee Breakwater Pile Fl (2) 5s (38° 20.66'S, 141°36.8'E).
- b) **8 knots** - east of the line referred to in a) above, to a line drawn between the Lee Breakwater light (38° 20.7'S, 141°37.18'E) and the Main Breakwater light (38° 20.67'S, 141°37.46'E).

Mariners are advised to navigate with caution within the harbour and to proceed at a safe speed at all times.

Captain David Shennan
Harbour Master
Office: 5525 0980
Mobile: 0439 209 120
E-mail: dshennan@portofportland.com.au