

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE: 07 NOVEMBER 2013

AUSTRALIA - VICTORIA

No.154-2013

PORT OF CORNER INLET & PORT ALBERT

TOORA CHANNEL

ALTERATION TO LIGHT CHARACTERISTICS

DATE: Effective Immediately.

DETAILS: Mariners are advised that the light characteristics of the Toora Channel Beacons – No. 1, 2, 3, 4, 5, 6, 7, & 8 - have been altered to flash synchronised.

The Toora Channel No. 1 and No. 2 lateral mark Beacons will flash synchronised Isophase 3 seconds (Iso.3s) with a nominal range of 4 Miles

The Toora Channel No. 3, 4, 5, 6, 7 & 8 lateral mark Beacons will flash synchronised Isophase 6 seconds (Iso.6s) with a nominal range of 2 Miles

The characteristics of the Toora Channel lateral mark Beacon No. 9 (Iso.G.2s) and the Barry Beach Channel Eastern Cardinal Mark No. 2 (VQ (3) 5s) remain unchanged

**CHARTS
AFFECTED:** AUS 181, AUS 182

**PUBLICATIONS
AFFECTED:** Admiralty Sailing Directions Australia Pilot Vol. II NP 14

**FURTHER
NOTICE:** This notice is self-cancelling and no further notice will be issued.

**CAPT BEVIS HAYWARD
HARBOUR MASTER**