## **NOTICE TO MARINERS**

## **GIPPSLAND PORTS**



The following Notice to Mariners is published for general information.

DATE: 21/11/2013

## AUSTRALIA - VICTORIA No.166-2013 PORT OF CORNER INLET & PORT ALBERT PORT ALBERT ENTRANCE REAR LEAD LIGHT LIGHT ALTERED

**DATE:** Effective Immediately.

**NOTICE** Temporary Notice No 011(T) of 2012 is referred and cancelled

CANCELLED:

**DETAILS:** Mariners are advised that the Port Albert Entrance Rear Lead light

(previously Oc.3s 12m 11M) has been altered to Oc.3s 11m 4M

and the Obscured sector has been removed.

The position of the rear lead has not been altered and remains;

Lat. 38° 43.618'S

Lon. 146° 38.988'E (Chart Aus. 182 WGS84)

Lat. 38° 43.7099'S

Lon. 146° 38.9102'E (Chart Aus. 181 AGD66)

CHARTS
AFFECTED:

AUS 181, AUS 182

**PUBLICATIONS** 

Admiralty Sailing Directions Australia Pilot Vol. II NP 14

AFFECTED:

This notice is self-cancelling and no further notice will be issued.

FURTHER NOTICE:

CAPT BEVIS HAYWARD HARBOUR MASTER