



VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

GEELONG, 1 JANUARY 2019

AUSTRALIA - VICTORIA

NO. 001(T)-19

VICTORIAN NOTICE TO MARINERS

NOTICES IN FORCE

- Date:** On the 1st January 2019
- Former Notice:** 001(T)-18 refers and is hereby cancelled.
- Details:** The following Victorian Notice to Mariners are in force.
- Notices can be downloaded from:
Victorian Regional Channels Authority (VRCA) website
www.vrca.vic.gov.au
- Victorian Ports Corporation Melbourne (VPCM) website
www.vicports.vic.gov.au
- Parks Victoria website
www.parks.vic.gov.au

<u>Notice No</u> <u>2005</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
68	Port of Hastings	Port of Hastings	Port of Hastings	Maritime Transport Security Regulations 2003 Restricted Zones – Crib Point & Long Island Point Jetties

<u>Notice No</u> <u>2006</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
53	Barwon Coast	Port of Barwon Heads	Barwon Heads River Entrance	Sand Movements – Possible Reduction in Depth

<u>Notice No</u> <u>2007</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
140(T)	Barwon Coast	Port of Barwon Heads	Port of Barwon Heads	Orungal Wreck Hazard – East of River Entrance

<u>Notice No</u> <u>2008</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
64(T)	Port of Hastings	Port of Hastings	Channel Off Sandy Point	Shoaling in Channel Between Nos. 13 and 15 Buoys
65(T)	Parks Victoria	Port Phillip	Outer Harbour	Abalone Farm Dislodged Pipelines, Leopold

<u>Notice No</u> <u>2013</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
173(T)	Gippsland Ports	Port of Corner Inlet & Port Albert	Port Anthony Marine Terminal	Berth Pocket Surveyed – Depths Declared Aids to Navigation Established

<u>Notice No</u> <u>2014</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
029(t)	Gippsland Ports	Port of Anderson Inlet	Vicinity of Point Smythe	Establishment of Speed Restriction Zone
213	Colac Otway	Port of Apollo Bay	Harbour Entrance	Harbour Entrance Reduced by Sand – Extreme Caution to be taken

<u>Notice No</u> <u>2015</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
088	Gippsland Ports	Port of Corner Inlet & Port Albert	Lewis Channel	Approach to Port Welshpool – Channel Shoaling
122(T)	MSV	Port Fairy	Griffith Island Light	Griffith Island Light - Warning
199(T)	MSV	Port Fairy	Taylor's Bay	Deployment of Cardinal Mark Buoys
217(T)	MSV	Port Fairy	Taylor's Bay	Exclusion Zone and Transit Lane Establishment
238	Barwon Coast	Local Port of Barwon Heads	Barwon River Entrance	Sector Light Aid to Navigation
255	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Bar	Warning to Vessel Operators Who Intend to Risk Bar Crossing at Anderson Inlet Ocean Entrance

<u>Notice No</u> <u>2016</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
038	Barwon Coast	Local Port of Barwon Heads	Barwon River Navigation Channel	Shallow Ground
134(T)	Parks Victoria	Port Phillip	Wyndham Harbour	Installation of Four Temporary Berthing Piles
147(T)	Parks Victoria	Port Phillip	Wyndham Harbour	Installation of One Temporary Berthing Pile
221	Gippsland Ports	Port of Anderson Inlet	Entrance Bar & Main Channel	Shoaling
227(T)	Gippsland Ports	Port of Gippsland Lakes	Lakes Entrance Bar	Rudder Lost
230	Gippsland Ports	Port of Anderson Inlet	Point Smythe	Speed Restriction Zone Buoys and Isolated Danger Buoy Removed
239(T)	MSV	Port Albert	Shoal Inlet Entrance	Temporary Light Established
250	Gippsland Ports	Port of Corner Inlet & Port Albert	Port of Corner Inlet & Port Albert	Harbour Masters Directions and Port Information Handbook Part 1 – August 2016 Edition
275	Gippsland Ports	Port of Corner Inlet & Port Albert	Corner Inlet Basin – Stockyard Channel	Navigation Aids Established – Navigation Aids Numbered
282(T)	Gippsland Ports	Port of Gippsland Lakes	Lakes Entrance Bar	Leads Altered
299(T)	Gippsland Ports	Port of Gippsland Lakes	Reeve Channel	Temporary light Buoy Established
328	Gippsland Ports	Port of Anderson Inlet	Anderson Inlet Bar	WARNING to Vessel Operations Intending to Risk Bar Crossings at Anderson Inlet Ocean Entrance
331	LINX Cargo Group	Port of Hastings	Western Port	Depths Reduced – 800 metres of No. 19 Buoy

<u>Notice No</u> <u>2017</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
80	Gippsland	Port of Gippsland Lakes	Bullock Island Narrows	Speed Restriction Aids to Navigation Established
125	Gippsland	Port of Corner Inlet & Port Albert	Port Albert Entrance Channel	Outer Starboard Hand Buoy – Light Reinstated to Normal Operation
177(T)	VPCM	Port of Melbourne	Swanson Dock East	Swanson Dock East Berth 1 – Rehabilitation Works
179(T)	MSV	Barwon Heads	Orungal Wreck	Cardinal Mark Buoy Off Station
198	Gippsland	Port of Gippsland Lakes	Port of Gippsland Lakes	Harbour Masters Directions and Port Information Handbook Part 2 – July 2017 Edition
245(T)	Parks Victoria	Port Phillip	Portarlington	Installation of Temporary Port Buoys within the Harbour
270(T)	Colac Otway	Port of Apollo Bay	Apollo Bay Harbour Entrance	Lead Lights at entrance to the Port of Apollo Bay are not aligned correctly with the current safe entrance channel.
278(T)	VPCM	Port of Melbourne	Williamstown Channel	Shoaling West North west of Beacon 22 Outside of Williamstown Channel
347(T)	Parks Victoria	Western Port	San Remo	Eastern Entrance – South East of Starboard Lateral Pile #1 - Shoaling
351	Barwon Coast	Local Port of Barwon Heads	Barwon River	Isolated Danger – Storm Water Pipe Outfall

<u>Notice No</u> <u>2018</u>	<u>Issued By</u>	<u>Region</u>	<u>Location</u>	<u>Details</u>
007(T)	MSV	Port Albert	Shoal Inlet	Light Destroyed
016(T)	VRCA	Port of Geelong	Corio Channel	Installation of Temporary Buoy in Corio Channel
017(T)	VRCA	Port of Geelong	Corio Channel	Installation of Second Temporary Buoy in Corio Channel
023	VPCM	Port of Melbourne	Yarra River	West Gate Bridge maintenance works
039(T)	VPCM	Port Melbourne	Port of Melbourne	Yarra Beacon 24 Unlit
057(T)	VPCM	Port of Melbourne	Port of Melbourne	Short Road tug berth project
058(P)	Colac Otway	Apollo Bay	Port of Apollo Bay	Notice - Entrance Sanding Up – Extreme caution to be taken
059(T)	Colac Otway	Apollo Bay	Port of Apollo Bay	Entrance and Harbour Depth Reduced by Sand
072(T)	VRCA	Port of Geelong	Corio Channel	Virtual Aids to Navigation in Corio Channel
124(T)	VPCM	Port of Melbourne	Port of Melbourne	Port Information Guide – March 2018 Edition
139	Port of Hastings	Port of Hastings	Western Port	Harbour Master's Directions
149(T)	Parks Victoria	Port Phillip	Williamstown	Kororoit Creek Entrance – Navigation Light – Non-operational
161	Gippsland	Port of Gippsland Lakes	Port of Gippsland Lakes	WARNING Paddle Craft and Small Vessel Operations Near the Ocean Access Entrance
201(T)	VPCM	Port of Melbourne	Webb Dock	Beacons 23, 82 and 84 restored to normal
204(T)	VPCM	Port of Melbourne	Webb Dock	Beacons 23, 82 and 84 restored to normal
205(T)	VPCM	Port of Melbourne	Port of Melbourne	Replacement of timber pile between Yarra River Beacon 26 and Beacon 28
206(T)	VPCM	Port of Melbourne	Swanson Dock one East	Precast panel removal completed
209	Gippsland	Port of Corner Inlet and Port Albert	Franklin River Channel	Navigation Aid Replacement Works
223(T)	VPCM	Port of Melbourne	Port of Melbourne	Maintenance works on Port Melbourne Channel Beacons E1, E2 and No. 6
224(T)	VPCM	Port of Melbourne	Swanson Dock West	Swanson Dock West 1 – Maintenance completed
242(T)	VPCM	Port of Melbourne	Swanson Dock 2 East	Swanson Dock 2 East – Maintenance shut
243	VPCM	Port of Melbourne	Port of Melbourne	Change to Harbour Master's Directions Edition August 2017
250	VPCM	Port of Melbourne	Port of Melbourne	Reporting point established north of Hovell Pile
254	VPCM	Port of Melbourne	Yarra River	Yarra River - Beacon 56 replaced by a buoy
258(T)	VPCM	Port of Melbourne	Swanson Dock East	Swanson Dock East Berth 2 – Rehabilitation Works
281(T)	MSV	Bass Strait	Port Fairy Bay	Deakin University wave buoy
296(T)	Parks Victoria	Port Phillip	Brighton	Middle Brighton Harbour – Submerged Navigation Hazard

303	Gippsland	Port of Corner Inlet and Port Albert	Lewis Channel – Port Welshpool Pier Reconstruction	Fish Habitat Area Established Aids to Navigation Established
306	VPCM	Port of Melbourne	Yarra River	Capricornia Dance and Bellarine Express trial of increased speed in Yarra River completed
311(T)	MSV	Bass Strait	Golden Beach	Melbourne University ocean bottom seismometer
312(T)	VPCM	Port of Melbourne	Appleton Dock	Appleton Dock rehabilitation works
314(T)	Gippsland	Port of Gippsland Lakes	Lakes Entrance Bar	Leading Line Light Intensity Trial
316(T)	VPCM	Port of Melbourne	Port of Melbourne	24-31 South Wharf sheet pile wall remediation works
322(T)	VPCM	Port of Melbourne	South Wharf	South Wharf 27 and 28 Stage 1 refurbishment works amendment
323(T)	VPCM	Port of Melbourne	Yarraville 6	Yarraville 6 – Maintenance Works
324(T)	VPCM	Port Phillip Heads	Fort West Beacon	Fort West Beacon remediation works complete
325(T)	Parks Victoria	Port Phillip	Frankston	Kananook Creek – Special Mark Pile Light – Non-operational
328(T)	VPCM	Port of Melbourne	Port of Melbourne	Amendment to Harbour Master’s Directions Edition 10 August 2017
332(T)	Portland	Port of Portland	Port of Portland - Anchorages	Anchorage
339(T)	VPCM	Port of Melbourne	Port of Melbourne	Maintenance dredging works
353(T)	Parks Victoria	Port Phillip	Patterson River	Nepean Highway Bridge Construction – Exclusion Zone - Extended
354(T)	Parks Victoria	Port Phillip	Patterson River	Loading Bay – Exclusion Zone - Extended
363	Port of Hastings	Port of Hastings	Western Port	Stony Point Channel Lights
371(T)	Parks Victoria	Western Port	Gentle Annie Channel	Gentle Annie Channel – No. 6 Port Lateral Buoy Missing
372(T)	Parks Victoria	Port Phillip	Indented Head	Jade Tiger Abalone Aquaculture Facility – East Cardinal Mark (Lit Buoy) - Missing
374	Gippsland	Port of Anderson Inlet & Anderson Inlet Bar	Port of Anderson Inlet & Anderson Inlet Bar	WARNING To vessel operators intending to risk bar crossing at Anderson Inlet Ocean Entrance
377	Gippsland	Port of Gippsland Lakes	Port of Gippsland Lakes	GAZETTE NOTICE – New Waterway Rule Transit Only Zone Established
384	Gippsland	Port of Gippsland Lakes	Hopetoun Channel	Aids to Navigation – Established – Relocated - Renumbered
386(T)	Parks Victoria	Port Phillip	Victoria Harbour	Port & Starboard Fixed Lateral Navigation Lights – Non-operational
388(T)	Parks Victoria	Port Phillip	Geelong	Eastern Beach – Installation of Temporary Swing Moorings
395(T)	Barwon Coast	Local Port of Barwon Heads	Barwon River	Barwon Heads Sailing Association Events exemption from certain rules
403(T)	MSV	Bass Strait	Torquay	Torquay - FADs

**Victorian Notice to Mariners are issued by a number of different Authorities.
This notice has been collated from the latest information held by the
Victorian Regional Channels Authority.
Information relating to the above notices is available at the
Victorian Regional Channels Authority Website.
Specific queries relating to Notices should be directed to the issuing Authority.**

Further Notice: Further notice will be issued

A handwritten signature in black ink, consisting of a large, stylized initial 'D' followed by a long, sweeping horizontal stroke that extends to the right.

**CAPTAIN DILIP ABRAHAM
HARBOUR MASTER
PORT OF GEELONG**

Victorian Notices to Mariners can be downloaded from the
Victorian Regional Channels Authority website www.vrca.vic.gov.au