

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.057(T) OF 2019

PORT OF CORNER INLET AND PORT ALBERT

TOORA CHANNEL No.9 LIGHT BUOY REPORTED UNLIT

DATE: 15th March 2019

DETAILS: Mariners are advised that Toora Channel No.9 Light Buoy (Iso.G.2s), in position;
Lat. 38° 43.368' S
Lon. 146° 22.618' E Datum WGS84
has been reported unlit.

Mariners are advised to take extra precaution when transiting to and from Barry Beach through the Toora and Barry Beach Channels. A further notice shall be issued as soon as repairs are made to the light.

Further Information can be obtained by contacting Gippsland Ports on 0351 500 500 or visit the Gippsland Ports Website at;
www.gippslandports.vic.gov.au

CHART

AFFECTED: Chart Aus. 182 – Approaches to Barry Beach.

PUBLICATIONS Waterways Online at Gippsland Ports website

AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: A further Notice will be issued

CAPT. BEVIS HAYWARD
HARBOUR MASTER