

VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 10 JUNE 2010

AUSTRALIA – VICTORIA

No. 60 – 2010

PORT PHILLIP (CORIO BAY)

LIMEBURNERS BAY CHANNEL

REPOSITION AND INSTALLATION OF NAVIGATION BUOYS

Date: Immediate

Details: Mariners are advised of new positions & new installations of navigation buoys at entrance to Limeburners Bay (Corio Bay). Buoy positions and details as follows;

PORT BUOYS:

No.	Approximate Position	Buoy Shape	Characteristic	Markings
1	38°04.386' S, 144°24.194' E	Pillar	Fl(3) R.6s	Day Marker
2	38°04.391' S, 144°24.123' E	Can	Fl(3) R.6s	
3	38°04.403' S, 144°24.086' E	Can		
4*	38°04.415 S', 144°24.051' E	Can		

*Buoy No. 4 has replaced a Special Mark 5 Knot Buoy.

STARBOARD BUOYS:

No.	Approximate Position	Buoy Shape	Characteristic	Markings
1	38°04.413 S', 144°24.196' E	Pillar		Day Marker
2	38°04.406' S, 144°24.132' E	Cone		
3	38°04.408' S, 144°24.102' E	Cone		
4	38°04.438' S, 144°24.064' E	Cone		

Mariners are advised to navigate Limeburners Bay Channel with caution. Mariners are advised to always ensure they check local weather & tidal conditions before they leave & take appropriate navigation charts & safety equipment.

Charts Affected: AUS 143, 153, 157

Further Notice: No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

**MAL POULTER
ACTING MANAGER OF OPERATIONS
BAYS AND MARITIME DIVISION**

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parkweb.vic.gov.au to view Notices.