

# NOTICE TO MARINERS

## GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE 21 JUNE 2010

AUSTRALIA - VICTORIA

No.065(T)/2010

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL

**DATE:** Effective Immediately.

**DETAILS:** Mariners are advised that the Starboard Hand Light Buoy at the Anderson Inlet Entrance has been damaged and is currently unlit.

POSITION: Lat 38 deg 38 min 40.0 sec  
Long 145 deg 42 min 56.6 sec

CHARACTERISTIC: Fl.G 3s 2m 2M

DATUM REFERRED: WGS84

**CHARTS  
AFFECTED:** AUS 801

**PUBLICATIONS  
AFFECTED:** Admiralty Sailing Directions Australia Pilot Vol II NP 14, NP83 (Vol K)

**FURTHER  
NOTICE:** A further notice will be issued.

**CAPT BRUCE GREEN  
HARBOUR MASTER**