

VICTORIAN NOTICES TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE 23 September 2010

AUSTRALIA – VICTORIA

No. 092 (T) – 2010

PORT PHILLIP

SOUTH CHANNEL – SUBMERGED STRUCTURE.

Date: With immediate effect.

Former Notice: 099 (T) – 07 refers and is cancelled.

Details: Mariners are advised that the single isolated danger buoy marking a submerged pile structure in approximate position (WGS 84) Latitude 38° 19.08' S Longitude 144° 49.61'E has been removed and replaced by 3 new isolated danger buoys, each having a light characteristic of Fl(2) 4s.

The buoys are positioned approximately 30 meters from the obstruction and form a triangle with the obstruction at its centre.

The submerged structure lies north of the South Channel boundaries between South Channel beacons No. 10 and No. 12.

Mariners are advised to proceed with caution when navigating in this area.

Charts AUS 143, AUS 158

Further notice: Further notice will be issued.



DAVID SHENNAN
HARBOUR MASTER