

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE:28/04 /2011

AUSTRALIA - VICTORIA

No. 067-2011

PORT OF ANDERSON INLET

ANDERSON INLET ENTRANCE

ALTERATION TO BUOYAGE

ERRATUM

DATE: Effective Immediately.

DETAILS: Previous Notice 060-2011 is referred and cancelled.

Mariners are advised that the No.2 Port Hand Light Buoy at the Anderson Inlet Entrance has been relocated and the characteristic altered.

The new position is: Lat. -38 deg. 38 min. 54 sec.
Long. 145 deg 42 min. 57 sec. (WGS84)

The new characteristic is: Fl.3s 2m 2M

**CHARTS
AFFECTED:** AUS 801

**PUBLICATIONS
AFFECTED:** NP14, NP83 (Vol. K)

**FURTHER
NOTICE:** This notice is self cancelling and no further notice will be issued.

**CAPT BRUCE GREEN
HARBOUR MASTER**