

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE:13/09/2011

AUSTRALIA - VICTORIA

No. 109-2011

PORT OF ANDERSON INLET

ANDERSON INLET ENTRANCE

DATE: With immediate effect

DETAILS: Mariners are advised that the No.1 and No.2 Buoys at the Anderson Inlet Entrance have been exchanged and relocated. The Isolated Danger buoy at Point Norman reef has been exchanged.

The No.1, No.2 and the Isolated Danger buoys have day marks and are lit.

POSITION

DETAILS:

No.1 Lat – 38 deg 38.608 min
 Long – 145 deg 42.910 min
 Fl.G 3s 2m 2M

No.2 Lat – 38 deg 38.903 min
 Long – 145 deg 42.944 min
 Fl.R 3s 2m 2M

Isolated Danger Position remains the same
 Fl(2) 5s 2m 2M

CHARTS

AFFECTED:

PUBLICATIONS

AFFECTED: AUS 801, NP14, Np83 (Vol K)

FURTHER

NOTICE: No further notice will be issued.

CAPT BRUCE GREEN
HARBOUR MASTER

NOTICE TO MARINERS

GIPPSLAND PORTS

