

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria

No. 113 (Temporary) of 2011

PORT CAMPBELL - Victoria

Date: EFFECTIVE IMMEDIATELY

Details:

Mariners are advised that the front and rear leads at Port Campbell will be temporarily removed for repair and maintenance on or about 20 September 2011 (for a period of up to 4 weeks).

Front Lead 38° 37.272' S 142° 59.484' E

Rear Lead 38° 37.188' S 142° 59.600' E

Mariners navigating in the vicinity or attempting to transit Port Campbell Bay should be mindful of the absence of the leads and exercise caution.

AUS Charts and publications affected:

AUS 141

Australia Pilot, Volume II NP14

Victorian Charts and Publications affected:

Nil

Further notice:

A further Notice will be issued.

Lisa Faldon
Director, Maritime Safety

20 September 2011