

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE:31/10/2011

AUSTRALIA - VICTORIA

No.124-2011

PORT OF GIPPSLAND LAKES

VICINITY OF LAKES ENTRANCE

WAVE RIDER BUOY

DATE: Effective Immediately.

REFER: Previous Notice - NTM. 050-2011

DETAILS: Mariners are advised that the wave monitoring buoy has been relocated to:

S 37° 54.9075'
E 147° 57.9379' (WGS 84)

A long elastic mooring system has been utilized to secure the buoy and consequently the position of the buoy may vary with tide and currents.

The buoy is displaying the following light characteristic:

Fl(5) Y 20s

Mariners are directed to navigate with caution when transiting the area, and to remain at least 200m clear of the buoy. No vessel is to moor to the buoy at any time.

CHARTS AUS 357 A – Bass Strait Oil Fields
AFFECTED:

PUBLICATIONS Australia Pilot Volume II (NP14), Admiralty List of Lights and Fog Signals. (Vol. K)

NOTICE TO MARINERS

GIPPSLAND PORTS



AFFECTED

FURTHER NOTICE This notice is self cancelling and no further notice will be issued.

ALAN SMITH
ACTING HARBOUR MASTER