

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE: 10/7/2012

AUSTRALIA - VICTORIA

No.103-2012

PORT OF GIPPSLAND LAKES

REEVES CHANNEL, LAKES ENTRANCE

BUOYAGE CHANGES

DATE: Effective Immediately.

DETAILS: Mariners are advised that the following navigation marks have been removed

No.2 Port pile (Fl.R.5s)
37°52.777'S
147°57.425'E

Port buoy (Fl.R.3s)
37°52.808'S
147°57.597'E

The following new navigation aids have been installed

Port buoy (Fl.R.3s)
37°52.840'S
147°57.637'E

Port buoy (Fl.R.3s)
37°52.867'S
147°57.409'E

Starboard buoy (Fl.G.3s)
37°52.806'S
147°57.406E

All positions are relative to WGS 84

NOTICE TO MARINERS

GIPPSLAND PORTS



CHARTS AUS 182.
AFFECTED:

PUBLICATIONS Australian Pilot Vol.II NP14
AFFECTED:

FURTHER This notice is self cancelling and no further notice will be issued.
NOTICE:

TIMOTHY HUNGERFORD-MORGAN
HARBOUR MASTER