



VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information

Port of Hastings 13th August 2012

Australia – Victoria

111 – T (2012)

Western Port - No 6 Buoy removed for maintenance

Effective; Immediately

Details; Mariners are advised that No 6 Buoy in the main shipping channel in Western Port, a port hand buoy in position approximate 38 ° 28.3 ' S, 145 ° 08.1 ' E has been removed for maintenance. Due to adverse weather conditions, it may take up to two weeks to replace. Mariners are advised to navigate with caution in the vicinity of the above position.

Further Notice; No further notice will be issued, this Notice is self cancelling.

A handwritten signature in blue ink, appearing to read "Shane Vedamuttu", with a long horizontal line underneath it.

**Capt Shane Vedamuttu.
Harbour Master
Patrick Ports Hastings**