

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria No. 162 (Permanent) of 2012 Port of Corner Inlet & Port Albert (Victoria) LIGHTHOUSE POINT

Date: EFFECTIVE IMMEDIATELY

Details: Mariners are advised that the Directional Light established below the Flashing White Range Light, at Lighthouse Point, showing Green, White & Red sectors has been amended as follows.

REFERENCE POSITION : Lighthouse Point Light : K2502
Lat. -38 deg. 50.638 min.
Long. 146 deg. 28.375 min. AGD66

Directional Light Centreline 277° 30'

Directional Light WRG 3s 35m 9M	G 272°30' -276° 30' (4°)
	W 276°30' -278°30' (2°)
	R 278°30' -282°30' (4°)

The flashing white range light characteristics remain the same.
Fl W. 5s 36m 17M Vis 187°-350° (163°)

Mariners are advised to maintain the centreline of the Directional Light 277 deg. 30 min. when transiting this region and be aware of further potential shoaling encroaching from the Northern Bank.

AUS Charts and publications affected:

AUS 181, AUS 802, AUS 357.
Admiralty Sailing Directions, Australia Pilot, Volume II NP14.
Admiralty List of Lights and Fog Signals Vol K NP83 (K2502).

Victorian Charts and Publications affected: Nil

Further notice:

No further Notice will be issued.

Peter Corcoran

Director, Maritime Safety

16 / 11 /2012