

The following Notice to Mariners is published for general information.



DATE 16th November 2012

AUSTRALIA - VICTORIA

No. 166 -2012

PORT OF BARWON HEADS

RECTIFICATION WORKS COMPLETE

NEW NAVIGATION CHANNEL MARKS in BARWON RIVER

Date:

Effective Immediately

Details:

Mariners are advised that works to rectify aid to navigation facilities in the Barwon River entrance and tidal channel have been completed, NTM 151(T) issued on 8th November 2012 is rescinded.

Mariners are advised that the **outer port hand lit pin** in the entrance of the Barwon River at position, *38° 17' 14.82" South and 144° 30' 20.79" East* (WGS 84) is lit with Fl.R.3s 3m 2M .

Mariners are advised the aids to navigation to mark the navigable river channel upstream (northward) from the Barwon River Bridge to the Ocean Grove Boat ramp a combination of lit marker buoys and lit marker pins as described here with approximate locaion;

Starboard lit buoy,	<i>38° 16' 55.02" South and 144° 29' 48.72" East</i> (WGS 84)
Starboard lit buoy,	<i>38° 16' 39.72" South and 144° 29' 50.82" East</i> (WGS 84)
Starboard lit buoy,	<i>38° 16' 35.34" South and 144° 29' 54.96" East</i> (WGS 84)
Port hand lit buoy,	<i>38° 16' 33.36" South and 144° 29' 58.68" East</i> (WGS 84)
Port hand lit pin (#4),	<i>38° 16' 29.91" South and 144° 30' 4.22" East</i> (WGS 84)
Port hand lit pin (#6),	<i>38° 16' 23.06" South and 144° 30' 14.29" East</i> (WGS 84)
Port hand lit buoy,	<i>38° 16' 11.40" South and 144° 30' 29.82" East</i> (WGS 84)
Port hand lit pin (#10),	<i>38° 16' 0.41" South and 144° 30' 35.45" East</i> (WGS 84)
Port hand lit pin (#12),	<i>38° 15' 52.94" South and 144° 30' 33.35" East</i> (WGS 84)

Mariners are advised to exercise caution when navigating in the area.

Further information can be obtained by contacting the Port of Barwon Heads on: (03) 5254 1118, usual office hours

**Charts &
Publications
Affected:**

AUS 143, Port Phillip,
Australian Pilot Volume II (NP 14) Page 68

Victorian Charts &

Publications affected: Schedule 10 Vessel Operating and Zoning Rules

Other Notices:

No. 53/06, 2006, issued 31/03/06, Port of Barwon Heads, River Entrance Sand Movements - Possible Reduction in Depth

No. 140(T), 2007, issued 02/11/07, Isolated hazard, wreckage awash at low tide, east of Barwon River entrance.

No. 129, 2012, issued 25/09/12, Barwon River Navigation Channel sediment movements – shallow ground

Further Notice:

No further notice will be issued.

This Notice to Mariners is issued by the Barwon Coast Committee of Management Inc. delegated Local Port Manager for the Port of Barwon Heads on behalf of the Department of Transport.

**R.A.Jordan
General Manager
Barwon Coast Committee of Management Inc.**

Contact; Port Officer, Warren Chapman
(03) 5254 1118 during usual office hours
mobile 0418 506 151
warren@barwoncoast.com.au