

# NOTICE TO MARINERS

**GIPPSLAND PORTS**



The following Notice to Mariners is published for general information.

DATE:03/12/2014

**AUSTRALIA - VICTORIA**

**No. 205/2014**

**PORT OF ANDERSON INLET**

**ANDERSON INLET ENTRANCE AND CHANNEL**

**NAVIGATION WARNING**

**DATE:** Effective Immediately.

**DETAILS:** Mariners are advised that the Outer Entrance Channel of the Anderson Inlet Entrance Bar has continued to shoal and its location is unreliable.

Vessel access through this bar structure is dangerous and entails risk.

In addition, shoaling has developed inside the outer bar region in vicinity of the Main Channel, these shoals attract swell and at times will break. Mariners are advised to navigate this region with the greatest of caution. Entry through the bar should not be attempted unless at high water, no swell and wind regimes less than 10 knots.

Further information can be obtained by contacting Gippsland Ports on 51 500500.

**CHARTS  
AFFECTED:** AUS 801

**PUBLICATIONS  
AFFECTED:** NP14, NP83

**FURTHER  
NOTICE:** A further notice will be issued.

**ALAN SMITH  
ACTING HARBOUR MASTER**