

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 24 December 2014
Australia – Victoria

No. 228 – 2014

Port of Port Phillip

East Port Phillip – Hampton to Fishermans Beach
Pile Driving Works Completed – New & Reinstated Aids to Navigation

Date: Immediate.

Previous Notices: 117(T)-2014 is referred. 170(T)-2013, 008-2014, 118(T)-2014, 120(T)-2014, 143(T)-2014 & 209(T)-2014 are referred and cancelled.

Details: Mariners are advised of the completion of pile driving and associated works to reinstate the aids to navigation lost in this winter’s storm event and to complete the latest phase of the Boating & Swimming Zone implementation.

The new and reinstated aids to navigation mark the offshore extent of the new Boating & Swimming Zones, 5 Knot Speed Limits, Shared Windsports Zone and No Vessels (Swimming Only) Zones.

The majority of the aids to navigation have been reinstated in the charted positions. The following tables identify new, modified and removed marks in the near shore areas of East Port Phillip, from Hampton to Fishermans Beach.

The locations (WGS84) of the new aids to navigation **installed** are:

General Location Description: Beaumaris & Fishermans Beach					
Latitude	Longitude	Function		Zone	Light Present
37°59.817’S	145°02.078’E	Special Mark	Conical Buoy	5 Knot & No Boating	Unlit
37°59.809’S	145°01.939’E	Special Mark	Conical Buoy	5 Knot & No Boating	Unlit
38°13.328’S	145°01.777’E	Special Mark	Pile	5 Knot & No Boating	Unlit
38°13.378’S	145°01.739’E	Special Mark	Pile	5 Knot & No Boating	Unlit

/continued

The locations (WGS84) of the redundant aids to navigation **removed** are:

General Location Description: Fishermans Beach					
Latitude	Longitude	Function		Zone	Light Present
38°13.346'S	145°01.766'E	Special Mark	Pile	5 Knot & No Boating	Unlit
38°13.392'S	145°01.728'E	Special Mark	Pile	5 Knot & No Boating	Unlit

The locations (WGS84) of the aids to navigation **modified** are:

General Location Description: East Port Phillip from Hampton to Fishermans Beach					
Latitude	Longitude	Location	Existing Function	Change	Light Characteristics
37°56.485'S	144°59.770'E	Hampton	Special Mark - unlit	Now lit	Fl Y 5s
37°59.519'S	145°01.414'E	Ricketts Point	West Cardinal - unlit	Now lit	VQ (9) 10s
37°59.595'S	145°02.608'E	Ricketts Point	East Cardinal - unlit	Now lit	Q (3) 10s
37°59.946'S	145°02.039'E	Ricketts Point	South Cardinal - unlit	Now lit	VQ (6) Fl 10s
37°59.946'S	145°02.039'E	Ricketts Point	South Cardinal - unlit	Now lit	Q (6) 15s
38°04.452'S	145°07.061'E	Patterson River	Port Lateral - lit	New Light Characteristics	Q.R
38°04.478'S	145°07.065'E	Patterson River	Starboard Lateral - lit	New Light Characteristics	Q.G
38°09.323'S	145°05.499'E	Davey's Bay	Isolated Danger - unlit	Now lit	Fl (2) 10s
38°10.547'S	145°04.416'E	Mount Eliza	West Cardinal - unlit	Now lit	Q (9) 15s
38°12.656'S	145°02.161'E	Mornington	Special Mark - unlit	Now lit	Fl Y 5s
38°13.417'S	145°01.584'E	Fishermans Beach	West Cardinal - unlit	Now lit	VQ (9) 10s

/continued

Mariners are advised to navigate with caution and at a speed commensurate with safe navigation within the vicinity of the new aids to navigation.

Charts & Publications

Affected: AUS 143 & 155

Further Notice: No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963.

On behalf of Parks Victoria may I take this opportunity to wish all mariners a happy Christmas and a safe 2015 on the water.

Ledene Ellis
Manager Maritime Infrastructure
Melbourne Region

Further information regarding the new Boating Zones, visit the Parks Victoria website at <http://parkweb.vic.gov.au/park-management/bay-and-waterways-management/boating-zones>

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.