

# VICTORIAN NOTICES TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 24 December 2014

AUSTRALIA – VICTORIA

No. 240(T) - 2014

PORT OF MELBOURNE

GELLIBRAND – GELLIBRAND SHOAL – PILE DAMAGED –TEMPORARY BUOY  
ESTABLISHED

**Date:** Effective immediately.

**Details:** Mariners are advised that the Gellibrand Shoal Pile structure (K 2338.22) has been damaged and light extinguished.

A temporary East Cardinal buoy BYB Qk Fl (3)10s 5M has been established in approximate position 37° 52.62 S 144° 54.88 ' E with top mark.

Waterways construction is to employ equipment including a crane barge to remove the damaged underwater steel pile on Saturday 27 December 2014.

**Mariners are advised to navigate with caution in the vicinity of the East Cardinal buoy and the works.**

**Charts & Publications affected:** AUS 154.

**Further notice:** A further notice will be issued.

ROY STANBROOK  
HARBOUR MASTER

This notice is a direction of the Harbour Master pursuant to section 232 of the Marine Safety Act 2010.  
The requirements of section 232(2) have been taken into account.