

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 30 December 2014
Australia – Victoria

No. 236T - 2014

Port of Port Phillip

Corio Bay - Outer Harbour/Point Wilson
Starboard Lateral Mark Damage - Light Non-Operational

Date: Immediate

Previous Notice: 170-2012 is referred and cancelled.

Details: Mariners are advised that the light with characteristics Fl.G.3s, located on the starboard lateral mark pile south of the Point Wilson Bank at approximate location 38°06.690'S, 144°31.000'E (WGS84), is temporarily non-operational.

The topmark has also been damaged.

The light and topmark will be re-instated as soon as practicable, weather permitting.

Mariners are advised to exercise caution while navigating in the area.

Charts & Publications

Affected: AUS 143 & 157

Further Notice: A further Notice will be issued upon reinstatement.

If you require any further information please contact Parks Victoria on 13 1963

Ledene Ellis
Manager Maritime Infrastructure
Melbourne Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.