

# VICTORIAN NOTICES TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 23 December 2014

AUSTRALIA – VICTORIA

No. 225(T) - 2014

PORT OF MELBOURNE

PORT PHILLIP – SOUTH CHANNEL – SHOAL AREAS

**Date:** Effective immediately.

**Details:** Mariners are advised that recent surveys in the South Channel have identified the following areas of shoaling:

- South Channel West between Beacon 2 and 4, depth of 15.24 m CD in position 38° 17.98' S and 144° 43.07' E. Approximately 30 m south of centreline.
- South Channel West between Beacon 4 and 6, depth 15.02 m CD in position 38° 18.24' S and 144° 44.79' E. Approximately 125 m north of centreline.

Mariners are advised to navigate with caution in the vicinity of the shoals.

**Charts & Publications affected:** AUS 144, AUS 158.

**Further notice:** A further notice will be issued.



ROY STANBROOK  
HARBOUR MASTER

This notice is a direction of the Harbour Master pursuant to section 232 of the Marine Safety Act 2010.  
The requirements of section 232(2) have been taken into account.