

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA - VICTORIA

NOTICE No. 221 - 2015

PORT OF GIPPSLAND LAKES

REEVE CHANNEL SHOALING – STARBOARD LATERAL BUOY
ESTABLISHED

DATE: 20th November 2015

DETAILS: Mariners are advised that recent bathymetric survey results have identified that migration shoaling has occurred between Reeve Channel Beacon number 3 (Q.G) and Beacon number 5 (Fl.G.4s).

To guard the shoaling a starboard hand lateral mark buoy, No 3A, with the flash characteristic Fl.G.5s has been established in position;
Lat. 37° 52.900' South
Lon. 147° 57.035' East Datum MGA94

Further details can be obtained from Gippsland Ports Lakes Entrance Office on 0351556900. The latest Bathymetric Survey for the Lakes Entrance Bar can be downloaded from the Gippsland Ports Website www.gippslandports.vic.gov.au

CHARTS Aus. 182
AFFECTED

PUBLICATIONS Admiralty Sailing Directions, Australian Pilot Vol.II NP14.
AFFECTED:

FURTHER No further notice shall be issued.
NOTICE:

CAPT. BEVIS HAYWARD
HARBOUR MASTER