

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 16 December 2015
Australia – Victoria

No. 251T – 2015

Port of Port Phillip

West Channel
Damaged No.6 Port Lateral Pile – Temporary Replacement

Date: Immediate.

Previous Notices: 248T - 15 is referred and cancelled.

Details: Mariners are advised of the temporary installation of a can-shaped port lateral buoy at approximate location 38°13.921'S, 144°43.477'E (WGS84), adjacent to the damaged No.6 port lateral pile in West Channel. The buoy is lit with the characteristics Fl(2)R.4s.

The port lateral buoy is a temporary aid to navigation pending repairs to the damaged No.6 pile located approximately at 38°13.922'S, 144°43.466'E (WGS84).

A temporary yellow light with the characteristics Q.Y has been installed on the damaged No.6 pile as the navigation light is not operational.

Mariners are advised to navigate with extreme caution within the West Channel pending the full reinstatement of the No.6 port lateral pile.

Charts & Publications

Affected: AUS 143 & 158

Further Notice: A further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices.