

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

Melbourne, 22 June 2017

Australia – Victoria

No. 175 (T) – 2017

PORT OF MELBOURNE

SWANSON DOCK EAST and WEST – NEW BOLLARD INSTALLATION

June 2017 - August 2017

**Date:** 22 June 2017

Refers: N/A

**Details:** Port users are advised that installation works, comprising of New Bollards are to

be carried out at Swanson Dock East and West are scheduled to commence from

23 June 2017 to August 2017.

Work will be conducted during daylight hours from the shore and scheduled around

shipping.

The works will be undertaken by Duratec Australia Pty Ltd, the primary point of

contact is Danny Roldan 0437 317 168.

More details are contained in the New Bollard Installation table below.

For more information, contact Melbourne VTS on 9644 9700.

Charts & Publications

affected: AUS 154

Further notice: Further notice will be issued.

SWANSON DOCK WEST - NEW BOLLARD INSTALLATION SCHEDULE				
DOCK	CHAINAGE	DETAIL	REMARK	
WEST BERTH 1 & 2	331	S103	ENSURE MINIMUM 1m FR0M	
			ADJACENT BOLLARD AT CH.329	
WEST BERTH 1 & 2	347	S103	SAFETY LADDER LOCATED AT	
			CH.348 TO REMAIN UNDISTURBED	
WEST BERTH 1 & 2	360	S103	ADJACENT FENDER ANCHORAGES	
			TO REMAIN UNDISTURBED	
WEST BERTH 3 & 4	615	S104	BOLLARD TO BE CENTERED	
			ABOVE HEADSTOCK	
WEST BERTH 3 & 4	630	S104	ADJACENT ANCHORAGES/	
	55 40	29 (49)	SERVICES NOT TO BE DISTURBED	
WEST BERTH 3 & 4	650	S104	BOLLARD TO BE CENTERED	
			ABOVE HEADSTOCK	
WEST BERTH 3 & 4	690	S104	BOLLARD TO BE CENTERED	
100		0	ABOVE HEADSTOCK	
WEST BERTH 3 & 4	710	S104	BREAKOUT TO INCLUDE EXISTING	
			SPALLED AREA	

SWANSON DOCK EAST - NEW BOLLARD INSTALLATION SCHEDULE				
DOCK	CHAINAGE	DETAIL	REMARK	
EAST BERTH 1 & 2	245	S105	ADJACENT ANCHORAGES/	
			SERVICES NOT TO BE DISTURBED	
EAST BERTH 1 & 2	255	S105	BOLLARD TO BE LOCATED	
			MIDWAY BETWEEN HEADSTOCKS	
EAST BERTH 1 & 2	270	S105	ADJACENT FENDER ANCHORAGES	
			NOT TO BE DISTURBED	
EAST BERTH 1 & 2	279	S105	ADJACENT SERVICES NOT TO BE	
			DISTURBED	
EAST BERTH 3	561	S106	BOLLARD TO BE CENTERED	
	7,777		ABOVE HEADSTOCK	
EAST BERTH 3	581	S106	BOLLARD TO BE CENTERED	
			ABOVE HEADSTOCK	
EAST BERTH 3	606	S106	BOLLARD TO BE CENTERED	
			ABOVE HEADSTOCK	

Andrew Hays Deputy Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.