

# NOTICE TO MARINERS

**GIPPSLAND PORTS**



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No. 182 OF 2017**

**PORT OF MALLACOOTA**

**BASTION POINT AND GOODWIN SANDS**

**NAVIGATION AID LIGHTING RETURNED TO SERVICE**

**DATE:** 29<sup>th</sup> June 2017

**DETAILS:** Mariners are advised that the unreliable navigation aid lights at Bastion Point Boat Ramp Channel and the Goodwin Sands, previously referred, have been returned to service.

Lights affected were :

Bastion Point Boat Ramp Channel

1. No.1 Light Beacon , (Fl.G 3s)  
Lat 37° 34.241' S. Long. 149° 45.884' E.
2. No.2 Light Beacon , (Fl.R 2s)  
Lat. 37° 34.251' S. Long. 149° 45.901' E.

Goodwin Sands

1. No.1 Light Beacon , (Fl.G 3s)  
Lat. 37° 31.769' S. Long. 149° 45.739' E.
2. No.3 Light Beacon , (Fl.G 4s)  
Lat. 37° 31.557' S. Long. 149° 45.716' E.
3. No.5 Light Beacon , (Fl.G 5s)  
Lat. 37° 31.365' S. , Long. 149° 46.239' E.

**PREVIOUS NOTICE** NTM 181 (T) of 2017 refers and is cancelled.

**FURTHER NOTICE:** No further Notice will be issued.

**ALAN SMITH**  
**ACTING HARBOUR MASTER**