

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No. 232 OF 2017

PORT OF GIPPSLAND LAKES

NORTH ARM LAKES ENTRANCE – BEACONS LIT

DATE: 7th September 2017

DETAILS: Mariners are advised that previously established Pile beacons Number 1, 2, 4 and 7 North Arm, have been lit. Details of the light beacons follows;

North Arm No1; Light Character (Fl.G.3s) in position;
Lat. 37° 52.941' S
Lon. 147° 58.172' E Datum WGS84
North Arm No2; Light Character (Fl.R.2.5s) in position;
Lat. 37° 52.958' S
Lon. 147° 58.074' E Datum WGS84
North Arm No4; Light Character (Fl.R.2.5s) in position;
Lat. 37° 52.911' S
Lon. 147° 58.150' E Datum WGS84
North Arm No7; Light Character (Fl.G.4s) in position;
Lat. 37° 52.801' S
Lon. 147° 58.482' E Datum WGS84

CHART Aus. 182 Plans in Victoria (South East Coast) – Lakes Entrance
AFFECTED:

PUBLICATIONS Admiralty Sailing Directions Australian Pilot Vol II NP14.
AFFECTED: Gippsland Ports Waterways Online at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER No further Notice will be issued.
NOTICE:

CAPT. BEVIS HAYWARD
HARBOUR MASTER