

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria

No. 007 of 2018

BASS STRAIT – PORT ALBERT – SHOAL INLET ENTRANCE

Date: EFFECTIVE IMMEDIATELY

Details:

Mariners are advised that the Shoal Inlet entrance light (Fl.2s) on the eastern side has been destroyed. (NTM 239-2016 (T))

The position of the light is:

Lat. 38° 40'.29" South

Lon. 146° 50'.7" East

(Datum WGS84)

The light be shall reinstated as soon as possible.

Mariners are advised to navigate with extreme caution in the vicinity of Shoal Inlet entrance during the hours of darkness.

AUS Charts and publications affected:

AUS 181 (Shoal Inlet Entrance)

Admiralty Sailing Directions, Australia Pilot Volume 2

Victorian Charts and publications affected:

Nil

Further notice:

A further Notice will be issued.



Rachel Gualano

Acting Director Maritime Safety Victoria

9 / 1 / 2018