

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria
No. 188 (T) of 2018
BASS STRAIT – TORQUAY

Date: EFFECTIVE IMMEDIATELY

Details: Mariners are advised that Notice to Mariners No. 050 (Temporary) of 2018 is referred and cancelled. The five special buoys have been temporarily withdrawn from the approximate positions (below) of an offshore recreational fishing reef, approximately two nautical miles East-South-East of Torquay.


All five buoys will be re-established in position, following the winter months, in November 2018.

1. 38° 19.934' S 144° 22.530' E
Special mark buoy solar marine lantern – 800mm diameter, 1.26m high, 2-3M.
Fl Y 5s.
2. 38° 19.940' S 144° 22.446' E
Special mark buoy solar marine lantern – 800mm diameter, 1.26m high, 2-3M.
Fl Y 5s.
3. 38° 19.993' S 144° 22.437' E
Special mark buoy solar marine lantern – 800mm diameter, 1.26m high, 2-3M.
Fl Y 5s.
4. 38° 20.021' S 144° 22.372' E
Special mark buoy solar marine lantern – 800mm diameter, 1.26m high, 2-3M.
Fl Y 5s.
5. 38° 20.075' S 144° 22.354' E
Special mark buoy solar marine lantern – 800mm diameter, 1.26m high, 2-3M.
Fl Y 5s.

AUS Charts and Publications Affected: Aus. 143, 788.

Victorian Charts and publications affected: Nil.

Further Notice: A further Notice will be issued.



CAMERON TOY
Acting Deputy Director, Operations
Maritime Safety Victoria

29/5/2018