

# NOTICE TO MARINERS

**GIPPSLAND PORTS**



The following Notice to Mariners is published for general information.

**AUSTRALIA - VICTORIA**

**No. 237 (T) 2014**

**PORT OF CORNER INLET & PORT ALBERT**

**PORT ALBERT ENTRANCE**

**FAIRWAY BUOY UNLIT**

**DATE:** With immediate effect

**DETAILS:** Mariners are advised that the Port Albert Entrance Fairway Light Buoy, is currently unlit

Charted Position  
Lat. 38° 44.392'S, Long. 146° 42.706'E

Datum  
WGS 84

Light Characteristics  
LFI 10s

**CHARTS AFFECTED** AUS 181, AUS 182

**PUBLICATIONS AFFECTED** Admiralty Sailing Directions Australia Pilot Vol II  
NP 14

**FURTHER NOTICE:** A further notice will be issued

**ALAN SMITH – ACTING HARBOUR MASTER**