

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 16 November 2018
Australia – Victoria

No. 319(T) - 2018

Local Port of Port Phillip

Portsea
Portsea Hole - Lit Special Mark Buoy - Missing

Date: **Immediate**

Details: Mariners are advised of a missing lit special mark (conical buoy), with light characteristics Fl.Y.5s, marking the south-western boundary of Portsea Hole - Port Phillip Heads Marine National Park, at approximate location 38°18.678'S, 144°42.568'E (WGS84).

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to continue to navigate with caution and within the speed limit near the Marine National Park.

Charts & Publications

Affected: AUS 143, 144, 158

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.