



VICTORIAN NOTICES TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE 06 May 2010

AUSTRALIA – VICTORIA

No. 044 – 2010

PORT OF MELBOURNE

PORT MELBOURNE CHANNEL – BEACONS E1 AND E2 MODIFIED.

Date: Effective 06 May 2010.

Former Notice: 166 - 09 refers and is superseded in reference to information provided about **Beacons E1 and E2.**

Details: Mariners are advised that following standard steel pile beacons with larger day marks and lights, flashing in unison, have been modified in the Port Melbourne Channel.

Port Melbourne Channel	Position(WGS 84)		Light Characteristics	Top Mark
	Latitude	Longitude		
<i>E1</i>	37° 57.795'S	144° 55.507'E	<i>Fl G 1.5s10m 8M</i>	Green Δ
<i>E2</i>	37° 57.788'S	144° 55.362'S	<i>Fl R 1.5s 10m 8M</i>	Red □

Charts & Publications Affected: AUS 143; AUS 144; AUS 155; AUS 158; and Admiralty List of Lights – NP 83, Vol K.

Further notice: No further notice will be issued.

DAVID SHENNAN
HARBOUR MASTER