

Victorian Notice to Mariners



Melbourne, 11 May 2010

The following Notice to Mariners is published for general information.

AUSTRALIA – VICTORIA – PORT CAMPBELL

NTM NO. 046(T)

LOCATION: PORT CAMPBELL - VICTORIA

**ITEM: NEW LEAD LIGHTS HAVE BEEN ESTABLISHED
REPLACING LEAD, POINT STURGESS.**

Date: WITH IMMEDIATE EFFECT

Details: Point Sturges,

New lead lights have been established replacing the existing lead.

New Leads are set at 050T degrees.

Front Lead, Iso B 1s, 12 m, 4M

Day Mark, Fluro Orange rectangle with white central strip, 6 m high.

Rear Lead, Iso B 4s, 12 m, 4M.

Day Mark, Fluro Orange rectangle with white central strip 12 m high, 4M range

Charts and publications affected:

AUS 141 AUS 349 AUS 787

Australia Pilot Volume II NP14, 2007 Port Campbell.

Further notice:

A further notice will be issued detailing accurate locations of the leads.

Diane Julie Bates

Director

Marine Safety Victoria