

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information and indicates that navigation buoys defining the limits of the Barry Beach channel have been temporarily shifted from station in order to allow access for the dredge 'Pelican' during the channel maintenance program.

An additional starboard hand lateral buoy has been established.

DATE 13 OCTOBER 2010

AUSTRALIA - VICTORIA

No.101(T)/2010

PORT OF CORNER INLET & PORT ALBERT

BARRY BEACH CHANNEL

DATE: Effective Immediately.

DETAILS: Temporary Positions are:-

Barry Beach Channel No.1 Light Buoy

Lat 38 deg 42 min 48.3 sec, Long 146 deg 22 min 55.7 sec

Barry Beach Channel No.2 Light Buoy

Lat 38 deg 43 min 18.4 sec, Long 146 deg 22 min 31.1 sec

Barry Beach Channel No.4 Light Buoy

Lat 38 deg 42 min 44.4 sec, Long 146 deg 22 min 50.4 sec

Toora Channel No.9 Light Buoy

Lat 38 deg 43 min 25.5 sec, Long 146 deg 22 min 39.6 sec

Additional Starboard hand lateral mark buoy has been established at:

Lat 38 deg 43 min 14.8 sec, Long 146 deg 22 min 40.8 sec

CHARACTERISTIC: FI(2)G 5s 2m 1M

DATUM REFERRED WGS84

CHARTS

AFFECTED: AUS 182

PUBLICATIONS

AFFECTED:

Admiralty Sailing Directions Australia Pilot Vol II NP14 & NP83 (Vol K)

NOTICE TO MARINERS

GIPPSLAND PORTS



**PREVIOUS
NOTICE:**

FURTHER No further notice will be issued.
NOTICE:

**CAPT BRUCE GREEN
HARBOUR MASTER**