



VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 13 OCTOBER 2010

AUSTRALIA – VICTORIA

No. 102 - 2010

PORT PHILLIP

YORKIES ROCK, SANDRINGHAM

POSITION OF ISOLATED DANGER BUOY ERRATUM

- Date:** Immediate
- Previous Notice:** 91-2010 refers
- Details:** Mariners are advised that the position of the isolated danger buoy, lit with characteristics Fl (2)10s marking Yorkies Rock off Sandringham is located approximately 37°57.163' S, 144°59.750' E (WGS84).
- Mariners are advised to exercise caution when navigating within the area, particularly between sunset and sunrise.**
- Charts Affected:** AUS 143, 155
- Further Notice:** No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

**MAL POULTER
ACTING MANAGER OF OPERATIONS
BAYS AND MARITIME DIVISION**

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parkweb.vic.gov.au to view Notices.

*Healthy Parks
Healthy People*