

# NOTICE TO MARINERS

## GIPPSLAND PORTS



**Mariners are advised that the Barry Beach Channel Directional Light has suffered storm damage and is currently unreliable.**

DATE 19 OCTOBER 2010

**AUSTRALIA - VICTORIA**

**No.105(T)/2010**

**PORT OF CORNER INLET & PORT ALBERT**

**BARRY BEACH CHANNEL**

**DATE:** Effective Immediately.

**DETAILS:** Mariners are advised that the Barry Beach Channel Directional Light (Dir.F WRG)  
Lat. – 38 deg. 42.4 min. Long. – 146 deg. 23.1 min. has suffered storm damage and is currently unreliable. Remedial works are being carried out.

**DATUM REFERRED** WGS84

**CHARTS  
AFFECTED:** AUS 182

**PUBLICATIONS  
AFFECTED:** Admiralty Sailing Directions Australia Pilot Vol II NP14 (Vol K)

**PREVIOUS  
NOTICE:**

**FURTHER  
NOTICE:** A further notice will be issued.

**CAPT BRUCE GREEN  
HARBOUR MASTER**