

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE:21/12/2011

AUSTRALIA - VICTORIA

No. 157(T)-2011

PORT OF CORNER INLET AND PORT ALBERT

PORT ALBERT ENTRANCE

NAVIGATION WARNING

DATE: With Immediate Effect.

DETAILS: Mariners are advised that the Outer Entrance Channel westward of the Outer Green Light Buoy and in vicinity of the Fairway Buoy has shoaled.

Mariners are advised to navigate this region with the greatest of caution. Passage should not be attempted unless at high water along with little or no swell.

Further information can be obtained by contacting Gippsland Ports on 51 500500.

CHARTS AUS 181, AUS 182.
AFFECTED:

PUBLICATIONS NP14, NP83 (Vol. K)
AFFECTED:

FURTHER A further notice will be issued.
NOTICE:

CAPT. TIM HUNGERFORD-MORGAN
HARBOUR MASTER