

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 16 November 2012

Australia – Victoria

No. 164-2012

PORT OF PORT PHILLIP – CORIO BAY

GEELONG

DEPLOYMENT OF PERMANENT LIT SPECIAL MARK YACHT COURSE BUOYS

Date: 16 November 2012

Details: Mariners are advised of the deployment of four special mark lit synchronising yellow, 800mm diameter ‘three sided’ shape buoys by Royal Geelong Yacht Club, to define yacht course rounding marks, at the following approximate locations detailed in the table below.

Buoy Identification	Latitude (WGS84)	Longitude (WGS84)	Location	Light Characteristics
CB3	38°08.456' S	144°22.870' E	420m NW of Limeburners Point (new)	Fl.Y 5s
CB4	38°08.524' S	144°22.144' E	150m off RGYC Marina (new)	Fl.Y 5s
CB5	38°06.234' S	144°22.764' E	100 – 150m to the east of #5 Corio beacon (existing temporary buoy)	Fl.Y 5s
CB6	38°06.501' S	144°24 190' E	Midway between CB1 and CB2 (new)	Fl.Y 5s

These four new yacht course rounding mark buoys are in addition to the previously deployed markers as detailed hereunder:

Buoy Identification	Latitude (WGS84)	Longitude (WGS84)	Location	Light Characteristics
CB1	38°05.560' S	144°24.200' E	North Channel Mark (existing)	Fl.Y 5s
CB2	38°07.616' S	144°24.184' E	Sth of Shipping Channel (existing)	Fl.Y 5s

Charts & Publications AUS 143, 153, 157

Affected:

Further Notice: No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Glenn Hooper
Acting Regional Manager
Bays and Maritime Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices.