

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 29 November 2012

Australia – Victoria

No. 177 – 2012

Port of Port Phillip

**SAFETY BEACH, DROMANA - BLAIRGOWRIE
INSTALLATION OF NEW AIDS TO NAVIGATION / REMOVAL OF REDUNDANT AIDS TO
NAVIGATION:**

Date: Immediate

Previous Notice: 045, 072 & 154 - 2012 are referred

Details: Mariners are advised of the installation of aids to navigation (piles) and the removal of redundant aids to navigation (piles) in the near shore area from Safety Beach, Dromana to Blairgowrie, as detailed in the following table.

The new aids to navigation mark the offshore extent of the 5 Knot speed limit; No Vessels (swimming only) zones and water ski access lane. The piles display retro-reflective banding, retro-reflective topmarks and regulatory signage.

Approximate locations (WGS84) of **NEW AIDS TO NAVIGATION INSTALLED:**

General Location Description – Safety Beach, Dromana to Blairgowrie					
Latitude	Longitude	Function		Light Present	Zone:
38° 21.443' S	144° 46.812' E	Pile	Special Mark - yellow	Unlit	5 Knot zone
38° 21.554' S	144° 47.338' E	Pile	Special Mark - yellow	Unlit	5 Knot zone
38° 19.154' S	144° 58.648' E	Pile	Special Mark - yellow	Unlit	5 Knot & No Vessels zone
38° 20.050' S	144° 56.903' E	Pile	Special Mark - yellow	Unlit	5 Knot zone
38° 20.238' S	144° 56.508' E	Pile	Special Mark - yellow	Unlit	5 Knot & Access lane
38° 20.265' S	144° 56.451' E	Pile	Special Mark - yellow	Unlit	5 Knot & Access lane
38° 20.378' S	144° 56.144' E	Pile	Special Mark - yellow	Unlit	5 Knot zone
38° 20.487' S	144° 55.830' E	Pile	Special Mark - yellow	Unlit	5 Knot zone
38° 20.757' S	144° 56.062' E	Pile	Special Mark - yellow	Unlit	5 Knot zone

Approximate locations (WGS84) of **REDUNDANT AIDS TO NAVIGATION REMOVED:**

General Location Description – Safety Beach, Dromana to Blairgowrie					
Latitude	Longitude	Function		Light Present	Zone:
38° 19.216' S	144° 58.910' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 20.322' S	144° 56.564' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 20.493' S	144° 56.055' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 20.701' S	144° 55.505' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 20.876' S	144° 54.991' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.088' S	144° 53.803' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.222' S	144° 53.211' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.377' S	144° 52.574' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.507' S	144° 52.039' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.646' S	144° 51.488' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.784' S	144° 50.917' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.874' S	144° 50.418' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.871' S	144° 49.017' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.859' S	144° 48.708' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.737' S	144° 48.100' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.608' S	144° 47.544' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 21.507' S	144° 46.967' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot zone
38° 19.185' S	144° 58.611' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot & No Vessels
38° 19.111' S	144° 58.706' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot & No Vessels
38° 20.014' S	144° 56.923' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot
38° 20.164' S	144° 56.555' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot & Access lane
38° 20.187' S	144° 56.492' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot & Access lane
38° 20.335' S	144° 56.143' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot
38° 20.473' S	144° 55.859' E	Pile	Special Mark - yellow	Unlit	5 Knot zone
38° 20.776' S	144° 54.928' E	Pile	Special Mark - yellow	Unlit	Redundant 5 Knot

Mariners are advised to navigate with caution within the vicinity of the aids to navigation.

Charts & Publications

Affected: AUS 143, 158

Further Notice: No Further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Ledene Ellis
Manager Maritime Infrastructure
Bays and Maritime Operations

Further information regarding the new Boating Zones at:

<http://parkweb.vic.gov.au/park-management/bay-and-waterways-management/boating-zones>

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices.