

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE: 18/07/2013

AUSTRALIA - VICTORIA

No.102(T)-2013

PORT OF ANDERSON INLET

ANDERSON INLET ENTRANCE

No.2 LIGHT BUOY REPORTED MISSING

DATE: Effective Immediately.

PREVIOUS NOTICE: NTM 77(T) is referred and cancelled

DETAILS: Mariners are advised that the No.2 Port Hand Light Buoy **Fl.(2) R 5s 2m 2M** at the Anderson Inlet Entrance is reported missing. The buoy measuring 2 metres x 1.5 metres is painted red and is unlit. The buoy may remain afloat until it washes ashore. Mariners are requested to report any sightings of the buoy to:
Assistant Harbour Master
Gippsland Ports – Port Welshpool
Phone 0428113324

PREVIOUS POSITION WGS84 Lat. 38° 38.952'
Long. 145° 43.531'

CHARTS AFFECTED: AUS 801

PUBLICATIONS AFFECTED NP14 NP38 (Vol K)

FURTHER NOTICE: A further notice will be issued

**CAPT BEVIS HAYWARD
HARBOUR MASTER**