

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 27 August 2013

Australia – Victoria

No. 118 – 2013

Port of Port Phillip

Patterson Lakes

Reduced Channels Depth and Minimal Lighting

Date: Immediate

Details: Mariners are advised of the general limited width and shallow depth conditions throughout Patterson Lakes.

A sand bar is present on the eastern side of the main channel south of the McLeod Road Bridge, located approximately 38°4.310' S 145° 8.150' E. The water depth at this location is reduced to approximately -1.08m Chart Datum (approximately 1.1m depth at lowest astronomical tide).

Depths may be further reduced at low tide by weather conditions, such as wind from an easterly Direction.

Mariners are also advised that there is no navigational lighting and an absence of amenity lighting on jetties throughout the Patterson Lakes.

Mariners are advised to navigate within the Patterson Lakes with extreme caution, ensuring they check the entrance depth, local weather, and tidal conditions before leaving and take appropriate navigation charts, lighting and safety equipment.

Charts & Publications AUS 143

Affected:

Further Notice: No further Notice will be issued.

If you require any further information please contact Melbourne Water on 131 722

Ledene Ellis
Manager Maritime Infrastructure
Melbourne Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices/ information.