

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 20 November 2015**  
**Australia – Victoria**

**No. 220(T) - 2015**

**Port of Port Phillip**

**Brighton**  
**R2 Recreation Buoy - Reinstated**

**Date:** Immediate

**Details:** Mariners are advised that the R2 recreational buoy positioned at the location below has been reinstated.

Latitude	Longitude	Buoy Identification	Light Characteristics
37° 54'.535'S	144° 56'.336'E	Yellow Conical Buoy (R2)	Fl(3)Y10s

**Mariners are advised to continue to exercise caution while navigating in the area.**

## Charts & Publications

**Affected:** AUS 143 & 155

**Further Notice:** No further Notice will be issued

**If you require any further information please contact Parks Victoria on 13 19 63.**



Victor Teoh  
**Senior Manager Local Ports and Waterways**  
**Melbourne Region**

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).