

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA - VICTORIA

No. 298 OF 2016

PORT OF GIPPSLAND LAKES

ENTRANCE TO CUNNINGHAME ARM

**SUBMERGED FENDER PILE RETRIEVED – NEW FENDER PILE
ESTABLISHED**

DATE: 19th October 2016 – Effective Immediately

**NOTICE
CANCELLED:** Notice to Mariners No 219(T) is referred and cancelled

DETAILS: Mariners are advised that the damaged and submerged steel fender pile at the Cunninghame Arm Starboard Entrance Light (Fl.G 3s) and jetty has been successfully retrieved.

A new Fender Pile has been driven in the same position, reinstating the Cunninghame Arm Entrance Light and jetty fender system.

Charted Position of the of the Cunninghame Arm Entrance Light is;
Lat. 37° 53.223' South
Lon. 147° 58.240' East WGS84 Datum

**CHART
AFFECTED:** Aus.182 – Plans in Victoria, South East Coast – Lakes Entrance.

**FURTHER
NOTICE:** No further Notice will be issued.

**BEVIS HAYWARD
HARBOUR MASTER**