

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 11 November 2016
Australia – Victoria

No. 315 – 2016

Port of Port Phillip

Sorrento

Sorrento Pier Front Lead Light reinstated with changed characteristics and new Rear Lead Light

Date: Immediate

Previous Notices: 146(T)-2016 is referred and cancelled.

Details: Mariners are advised the Front Lead Light positioned at approximate location (WGS84) below, is now reinstated with changed light colour and characteristics.

There is also now a Rear Lead Light positioned at approximate location (WGS84) below, with the following characteristics. These lights are on a bearing of 169°48'.

| Description | Latitude | Longitude | Characteristic | Colour |
|--------------------------------|---------------|----------------|---------------------------|--------|
| Front Lead Light Sorrento Pier | 38° 20.119' S | 144° 44.747' E | Iso 2 (1sec on 1sec off) | Blue |
| Rear Lead Light Sorrento Pier | 38° 20.155' S | 144° 44.740' E | Iso 8 (4sec on 4 sec off) | Blue |

| Day shape colour | Day shape type |
|---|-----------------------------|
| Orange, White, Orange (200mm, 200mm, 200mm) | 3M diamond grade reflective |

Mariners are advised to navigate with caution when in the vicinity of Sorrento Pier.

Charts & Publications

Affected: AUS 143 & 158.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 19 63

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.